

MSP/MCD DECAL APPLICATION POLICY FOR SCHOOL BUSES

SERVICE DOOR

Service Door: General

YELLOW: Flexible material on vertical closing is defective.

YELLOW: Door is not maintained as manufactured.

RED: Door fails to operate manually.

RED: Door does not open or close properly. *NST-SBI 11.78*

RED: Door control handle does not lock in the closed position. *NST-SBI 11.78*

RED: Door is equipped with a padlock or similar non-OEM locking device. (Excludes vehicles equipped with an interlock system.) *NST-SBI 11.78*

Handrails Service Door: General

RED: Any missing handrail. *NST-SBI 11.75*

RED: Any handrail improperly installed or loose.

RED: Any handrail that fails the nut/drawstring test or has not complied with the recall.
NST-SBI 11.75